

Early Dunlop JH-1 schematic.

PCB is a Dunlop Cry Baby Rev C. one.

* : soldered across pot lugs

** : soldered across the 33k resistor (component side)

*** : soldered afterwards (remelting traces) . Though the unit is most probably stock, I can't tell for sure if this has been done in the factory.

Drawn by lolbou from unit AA-01G937

