


Revisions:
 0.1-0.2 - Corrected missing connection between IC1 pins 5 and 13, added missing connection dots



- Notes:
- This schematic may contain errors and is subject to change without prior notice
 - Traced from unit with serial starting 20131003
 - Board Marked EC-D47 Rev. A
 - Component numbering according to PCB
 - Ferrite bead specs not known
 - Tone section capacitors are ceramic
 - C16 & C17 capacitors are not mounted

EH BMP w/ Tone Wicker
 V.0.2 - 5.8.2014
 mirosol/freestompboxes.org