



Alignment Procedure:  
 Drive switch to up position  
 Boost switch to normal  
 Peak control fully ccw  
 Range to Low  
 Mode to BP  
 Input 400mVp-p 2KHz  
 Adjust gain control for the  
 overload LED just glow  
 Adjust trim pot to get maximum  
 (about 800mVp-p) at effect output  
 Switch range to Hi  
 Check the output peaks @4KHz  
 Check all modes output

# Electro Harmonix Q-Tron

Special thanks to the IP Troll