


NOTES: LFO corrections by Diego Araya
ICs are RC 4558 or TI 4558

All capacitors listed in Mircofarads unless noted.

2 pedals used to trace schematic () denotes part discrepancies between the units.

Musitronics Corp.	
Mu-Tron Phasor II	Pg. 2 of 2
Drawn By: Richard Boop	Rev. 01 - 20 - 2008



NOTES: LFO corrections by Diego Araya ICs are RC 4558 or TI 4558

All capacitors listed in Mircofarads unless noted.

2 pedals used to trace schematic () denotes part discrepancies between the units.

Musitronics Corp.	
Mu-Tron Phasor II	Pg. 1 of 2
Drawn By: Richard Boop	Rev. 01 - 20 - 2008