



Image copyleft mirosol

Raygun FX Octavia Phuzz
 Traced 2015-03-15
 Original unit had 9V to volume pot lug 1 and
 was missing a LED resistor. Switching is standard
 true bypass with input left hanging.